

Oil Field Environmental Incident Summary

Incident: 20151006130818 **Date/Time of Notice:** 10/06/2015 13:08
Responsible Party: PETRO HARVESTER OPERATING COMPANY, LLC
Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC
Well Name: SADIE HUFF 1
Field Name: WOBURN **Well File #:** 1860
Date Incident: 10/6/2015 **Time Incident:** 11:00 **Facility ID Number:**
County: BURKE **Twp:** 162 **Rng:** 90 **Sec:** 4 **Qtr:** SE NW
Location Description: Approximately 1.6 miles SW of the town on Flaxton.

Submitted By: Gary Watson

Received By:

Contact Person: Mark Bonnie
103 1st Avenue NE
Mohall, ND 58761

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1.6 Mile

Distance Nearest Water Well: 1.6 Mile

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Barrels	1.5	Barrels		
Brine	1.5	Barrels	1.5	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No health hazard or explosive risk.

Areal Extent:

Potential Environmental Impacts:

All released fluids were contained within the diked area. Most of the fluid was collected in the wellhead cellar.

Action Taken or Planned:

Pressure (250 psig) will be bled of the casing valve to a hot oil unit. The well will be killed with produced water and a service rig moved in to pick-up on the tubing and repair the wellhead. The released fluids will be vacuumed up and the affected facility soil will be scraped up and hauled to an approved disposal facility.

Wastes Disposal Location: Approved waste disposal facility.

Agencies Involved:**Updates**

Date: 10/7/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location within the diking according to the report. NDIC retains oversight.